

03500.016001.



Cofe
S
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TOMOYA OHNISHI)
Appl. No.: 10/002,291)
Filed: December 5, 2001)
For: IMAGE DISPLAY APPARATUS)
HAVING A POTENTIAL)
REGULATING ELECTRODE,)
AN ANODE, AND A SPACING)
MEMBER, FOR SUPPRESSING)
UNDESIRED DISCHARGE)
U.S. Patent No.: US 6,803,717 B2)
Issued: October 12, 2004)
) September 16, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
SEP 26 2005

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

09/20/2005 EAYALEW1 00000051 6803717

01 FC:1811


100.00 DP

SEP 27 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank A. DeLucia
Attorney for Patentee
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
NY_MAIN 513741v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 1 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 24, "inventors" should read --inventor--;
Line 25, "have" should read --has--;
Line 29, "inventors have" should read --inventor has--; and
Line 32, "inventors have" should read --inventor has--.

COLUMN 2

Line 53, "inventors" should read --inventor--.

COLUMN 3

Line 42, "may-preferably" should read --may preferably--, and
"include" should read --includes--
Line 54, "referred" should read --referred to--; and
Line 56, "(hereupon" should read --(hereinafter,--.

COLUMN 4

Line 52, "Hereupon," should read --Hereinafter,--.

COLUMN 6

Line 45, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 2 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 4, "membrane is" should read --membrane--; and
Line 24, "an" should read --a--.

COLUMN 8

Line 32, "referred" should read --referred to--; and
Line 36, "fist" should read --first--.

COLUMN 9

Line 21, "ordinary" should read --ordinarily--.

COLUMN 10

Line 54, "is" should read --are--; and
Line 56, "electrode" should read --electrodes--.

COLUMN 11

Line 58, "inventors" should read --inventor--; and
Line 61, "inventors" should read --inventor--.

COLUMN 12

Line 1, "inventors" should read --inventor--;
Line 7, "inventors" should read --inventor--; and
Line 10, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,803,717 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
NY_MAIN 513741v1

→

SEP 27 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 3 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 37, "a" should read --an--.

COLUMN 15

Line 11, "limited" should read --limited to--; and
Line 58, "(hereupon" should read --(hereinafter,--.

COLUMN 17

Line 8, "rage" should read --range--.

COLUMN 19

Line 36, "inventors" should read --inventor--;
Line 42, "inventors" should read --inventor--; and
Line 45, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

SEP 27 2005

➡

SEP 27 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004

INVENTOR(S) : TOMOYA OHNISHI

Page 4 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 23, "plate" should read --paste--;
Line 36, "inventors" should read --inventor--;
Line 39, "inventors" should read --inventor--;
Line 43, "inventors" should read --inventor--;
Line 44, "potions" should read --portions--;
Line 45, "inventors" should read --inventor--;
Line 47, "inventors" should read --inventor--;
Line 52, "inventors" should read --inventor--;
Line 54, "inventors" should read --inventor--; and
Line 60, "inventors" should read --inventor--;

COLUMN 21

Line 64, "inventors" should read --inventor--; and
Line 67, "inventors" should read --inventor--.

COLUMN 22

Line 6, "inventors" should read --inventor--;
Line 11, "inventors" should read --inventor--; and
Line 14, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
NY_MAIN 513741v1

SEP 27 2006



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004

INVENTOR(S) : TOMOYA OHNISHI

Page 5 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23

Line 18, "inventors" should read --inventor--;
Line 21, "inventors" should read --inventor--;
Line 29, "inventors" should read --inventor--; and
Line 35, "inventors" should read --inventor--.

COLUMN 24

Line 18, "inventors" should read --inventor--;
Line 24, "inventors" should read --inventor--;
Line 28, "inventors" should read --inventor--;
Line 32, "inventors" should read --inventor--; and
Line 62, "surely" should read --surely be--.

COLUMN 26

Line 5, "(Ω/□," should read --(Ω/□),--; and
Line 47, "eve" should read --even--.

COLUMN 27

Line 40, "than" should read --other than--.

COLUMN 28

Line 43, "10⁴ (Ω/□)." should read --10¹⁴ (Ω/□).--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
NY MAIN 513741v1

SEP 27 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE


PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 6 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 2

Figure 2, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
NY_MAIN 513741v1

SEP 27 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004

INVENTOR(S) : TOMOYA OHNISHI


Page 7 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 8

Figure 11, should read

FIG. 11 PRIOR ART



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION


PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 8 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 9

Figure 12, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
NY MAIN 513741v1



SEP 27 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION


PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 9 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 10

Figure 13, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004

INVENTOR(S) : TOMOYA OHNISHI

Page 1 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 24, "inventors" should read --inventor--;

Line 25, "have" should read --has--;

Line 29, "inventors have" should read --inventor has--; and

Line 32, "inventors have" should read --inventor has--.

COLUMN 2

Line 53, "inventors" should read --inventor--.

COLUMN 3

Line 42, "may-preferably" should read --may preferably--, and
"include" should read --includes--

Line 54, "referred" should read --referred to--; and

Line 56, "(hereupon" should read --(hereinafter,--.

COLUMN 4

Line 52, "Hereupon," should read --Hereinafter,--.

COLUMN 6

Line 45, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004

INVENTOR(S) : TOMOYA OHNISHI

Page 2 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 4, "membrane is" should read --membrane--; and
Line 24, "an" should read --a--.

COLUMN 8

Line 32, "referred" should read --referred to--; and
Line 36, "fist" should read --first--.

COLUMN 9

Line 21, "ordinary" should read --ordinarily--.

COLUMN 10

Line 54, "is" should read --are--; and
Line 56, "electrode" should read --electrodes--.

COLUMN 11

Line 58, "inventors" should read --inventor--; and
Line 61, "inventors" should read --inventor--.

COLUMN 12

Line 1, "inventors" should read --inventor--;
Line 7, "inventors" should read --inventor--; and
Line 10, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 3 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 37, "a" should read --an--.

COLUMN 15

Line 11, "limited" should read --limited to--; and
Line 58, "(hereupon" should read --(hereinafter,--.

COLUMN 17

Line 8, "rage" should read --range--.

COLUMN 19

Line 36, "inventors" should read --inventor--;
Line 42, "inventors" should read --inventor--; and
Line 45, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004

INVENTOR(S) : TOMOYA OHNISHI

Page 4 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20

Line 23, "plate" should read --paste--;
Line 36, "inventors" should read --inventor--;
Line 39, "inventors" should read --inventor--;
Line 43, "inventors" should read --inventor--;
Line 44, "potions" should read --portions--;
Line 45, "inventors" should read --inventor--;
Line 47, "inventors" should read --inventor--;
Line 52, "inventors" should read --inventor--;
Line 54, "inventors" should read --inventor--; and
Line 60, "inventors" should read --inventor--;

COLUMN 21

Line 64, "inventors" should read --inventor--; and
Line 67, "inventors" should read --inventor--.

COLUMN 22

Line 6, "inventors" should read --inventor--;
Line 11, "inventors" should read --inventor--; and
Line 14, "inventors" should read --inventor--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 5 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23

Line 18, "inventors" should read --inventor--;
Line 21, "inventors" should read --inventor--;
Line 29, "inventors" should read --inventor--; and
Line 35, "inventors" should read --inventor--.

COLUMN 24

Line 18, "inventors" should read --inventor--;
Line 24, "inventors" should read --inventor--;
Line 28, "inventors" should read --inventor--;
Line 32, "inventors" should read --inventor--; and
Line 62, "surely" should read --surely be--.

COLUMN 26

Line 5, "(Ω/□," should read --(Ω/□),--; and
Line 47, "eve" should read --even--.

COLUMN 27

Line 40, "than" should read --other than--.

COLUMN 28

Line 43, "10⁴ (Ω/□)." should read --10¹⁴ (Ω/□).--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2

DATED : October 12, 2004


INVENTOR(S) : TOMOYA OHNISHI

Page 6 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 2

Figure 2, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI


Page 7 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 8

Figure 11, should read

FIG. 11
PRIOR ART



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION


PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 8 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 9

Figure 12, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION


PATENT NO. : US 6,803,717 B2
DATED : October 12, 2004
INVENTOR(S) : TOMOYA OHNISHI

Page 9 of 9

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

SHEET 10

Figure 13, should read



MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,803,717 B2

No. of add'l. copies
@ 30¢ per page